


gap between the rails up by the light pole and they came along and put a short piece in behind the existing rail—what good is that?

On the right, somebody busted right through there, because there were two pieces of rail which were not tied together. There should have been one continuous stretch.

Here you see some telephone poles in front of guardrails. You can say why did somebody do that? It looks silly. Someone might say



that maybe the property behind that guardrail belongs to people who do not want them there. Well, I thought of that, so I took this picture. There are many poles here.

