


Now, this is a steel pole, 14 inches in diameter, that will split you in half. There is a guardrail on the left and there is a whole bunch of trees back further in the picture, but you barely see them. Every one of these is in front of the guardrail.



There must be something wrong when you see things like this on the highway, especially on new highways. All of these guardrails are installed wrong.

