

Here you see a job where they have a temporary overpass. The guardrail has been installed properly and a car can slide by this particular obstacle. This is good.



But others are not. Some of these stand like this for 2 or 3 months and provide no protection, they are hazards. There is more hazard now than before they started. They are not using this particular location, this area here; they leave it over the weekend. They should replace this guardrail here to give the motorist a break.

