


Here you see a line in the fence in the background. This is a new bridge that is being built on top here.



There is the finished job. There used to be a guardrail here, but now that they have finished the job you have an unprotected abutment. This is a serious matter. If we do any new work, we are going to have to protect it.

