

Mr. O'HARA. Yes, they are generally right at the edge of the shoulder or a couple feet beyond depending on the shoulder area available.

Mr. W. MAY. All right.

Mr. O'HARA. This is what happened. Here is a pickup truck which ran off the highway at 3 o'clock in the afternoon, and struck the I-495 route marker. As you can see, the sign is still there.



As you can see from this slide, the pickup truck is pretty heavily damaged.

Mr. BLATNIK. Is this the same truck?

