


Mr. O'HARA. Yes. This is a closeup of the same truck. The driver received severe injuries in this accident.

After the accident, the sign was put back up. This is a photograph I took subsequently of the exact location of the accident scene which we just looked at. Now the sign is mounted on one 4-inch I-beam.



And this is what can happen to a vehicle which hits one 4-inch I-beam. This was a 1966 accident. The driver in this car was severely injured.

