


This is the base of that sign support. And you can see that the support has not been damaged.



The photograph speaks for itself as to the vehicle.

Mr. BLATNIK. The vehicle is totally demolished and just a few scratch marks on the concrete and on the I-beam, is that right?

Mr. O'HARA. Yes.

Mr. W. MAY. That accident occurred prior to the time you took your photographs?

Mr. O'HARA. Yes, it did. This accident occurred in October of 1966 and I took this photograph (fig. 3-17) in late December, or early January of 1967.

Mr. W. MAY. So your photograph depicts the way the situation stands today?

Mr. O'HARA. That is correct. That is the way it is now.