

Since we are speaking of guardrails, this is the same accident, and you can see that the guardrail did not stop him from getting behind and up to that sign support. Because here is the guardrail you saw in the first photograph. The car is in behind it.

