


It extended beyond the car. One person was killed and one person severely injured. The same type guardrail installation.



We can go to Virginia and we can find similar situations. Here you have a guardrail approaching a bridge. Here is a guardrail not flared back on the left. The guardrail runs up to the bridge parapet. It is not anchored. On this side the guardrail extends back somewhat like an arrow. It ends at the bridge parapet. In this case they have taken the shoulder through the bridge.

