


what happens to a vehicle when it hits a guardrail. There were similar photographs from Route 495 in Virginia, but this one best illustrated the point.

This is a typical installation of a guardrail where it meets a bridge parapet on the Maryland side of the Capital Beltway. This particular photograph was taken in December 1966.



In checking the accident records I found there have been accidents at locations similar to that. This one occurred in December 1965, on the beltway where it crosses University Boulevard. This is in the area just west of the Baltimore-Washington Parkway. This accident resulted in one death and one injury.

