


This is a location where I took a photograph in January 1967. The road at this point, which is just south of River Road as you are proceeding toward Virginia on the beltway, crosses over the Cabin John Parkway. The road begins to curve to the right. And on the left your guardrail runs up to the bridge parapet. And on the right the guardrail is again like an arrow, and the shoulder is dropped as you go through the bridge. The guardrail goes up to the bridge parapet and is not anchored.



And again checking the police records I found that that location was the scene of a fatality in 1966 where the vehicle smashed into the guardrail and was led into the bridge parapet. I cannot show you a photograph of the vehicle. It was totally demolished and would not serve any purpose at this point.

