


in March and April of this year I found that in September 1965 there had been a fatal accident at the very location which I have just shown you. This occurred at 4:30 in the afternoon. Now this is just illustrative of the type of damage and injury that can be sustained when you hit a bridge pier such as this.



This is a photograph of the approach to the George Washington Parkway on the Virginia side of the beltway. In this area the road is curving slightly to the right and again you will see there is no guardrail to shield a motorist who might happen to wander down in this area [indicating]. Nor is there a guardrail on the southbound

