




Here is a closeup shot. You can see the bolt still on the post and the rail actually pulled off the post coming right through without the washer. With the washer in there you would have had at least benefit of a little more guardrail than was working at the time of this collision.

Moving back to the subject project——

Mr. CONSTANDY. Interstate 80?

Mr. PRISK. That is right, in Ohio.

Mr. CONSTANDY. January 1967?

Mr. PRISK. That is right. True.

