

This rail—look at it a little bit farther—here is an installation where there are some light poles involved. The one that you see first, beyond the end of this rail, has a frangible base, transformer base in there. This one is a steel pole and so are the others behind the guardrail.

During the course of the work, the contract was changed to introduce these frangible bases in those places where the light poles were exposed.

One thing that you will notice is that there is a separate guardrail around each post installation and some of the other places, and that, again, begins to bring some concern about the continuity of the rail and desirability of closing up gaps that we see there.

