


Here is a view on that same structure and you will see that someone did get up on top of this safety walk and put a pretty good dent on this steel channel that runs along the top.

This is that narrow section of bridge.



Here is another one, still another bridge at the same width, I might say. There is a marker out here.

Mr. CONSTANDY. What is that marker, Mr. Wilson? The panel with the black and white stripes?

