Mr. Prisk. Moving along here, we found this condition at one structure which is certainly a part of the cleanup illustrated on jobs that are still open to traffic and not fully completed as far as all the safety equipment on the highway is concerned. It is disturbing to find conditions like this on highways that carry large volumes of traffic. This one is I-95 in Rhode Island.

