


This is a case where that treatment that I mentioned, I believe, has been accomplished. There has been a type of anchorage into the end of the wall and post, driven right along side of the end wall of the parapet. This again provides support.



We see here one completely without any anchorage. This is overpassing a more local street.

