


765

This is that pole knocked down showing the extent of damage there. Bending the lower part of this aluminum pole.

Of course, the luminaire itself, the glassware, is broken as it comes down.



Here is another one—this is off the project but still on Interstate 95—indicating a pole knocked down. It is rather interesting to us that in the very short distance that we are looking at here, we saw four or five light poles actually laying along the roadside as this one appears.

