


Here are some of the things that Mr. Wilson mentioned, the same narrow clearance to the edge of pavement, and 1 or 1½ feet, possibly 2 feet at the very most, showing off the edge of that pavement the unprotected posts or base.



Here is one upon the parapet wall of the bridge which does afford the protection by the structure that is there.

