


Here it shows how this hinge joint actually operate when it is struck by a car. It lets loose, and the web of the I-beam is cut through, all except this flange here on the back, on the underneath side. You end up with that kind of situation.



It almost looks like a war scene. In this particular case the sign was struck, the driver went on his way, and there was no record of the accident filed. The newspaper in the area became a little bit curious, and with some little detective work finally located the car in a garage, found out there was very little damage to the car, talked to the driver. He was completely uninjured, and had no difficulty at all at this point,

