


A special situation, of course, introduces itself if you find rock alongside, and in the severe cases here this has been cut back to 20 or 25 feet from the pavement edge, still stands there, somewhat of a hazard.



This on the Indiana projects shows relatively good slopes to the roadside, carrying on out all the way to the right-of-way line.

