



This happens to be a picture of the first sign that was hit after they started installation of these along the highway, and it just happens that this particular sign was put in or the installation was completed at 5 o'clock one afternoon. The driver struck this sign at 6:30 the next morning, and this is a picture or view of the front of the vehicle after impact.



Dr. KEESE. The Texas Highway Department contacted this individual and asked him what the effect of hitting the sign was, and he replied it was about like hitting a chuckhole in the road. He also said: