

1073

This begins a series of pictures of the breakaway luminaire that was struck by a vehicle; to compare the type of accident that you get here with that picture that Dr. Rowan showed a moment ago.



This is the frangible base that was shown.

