

1117

grees, the car was redirected properly and front wheel damage kept the car in a hard right turn. Peak vehicle deceleration was about nine gs.

These sequences show an early test of the box beam bridge rail. This school bus, loaded with sand bags and weighing 14,000 pounds, hit the barrier at thirty miles an hour and twenty degrees. Redirection was excellent, and peak

