

1181

This is another photograph taken in Rhode Island which shows the existence of a formidable piece of rock which was left off the right shoulder at a distance of some 15 feet in an attempt to provide esthetics. This was a common situation on that project.



This is again in Georgia. It is a median structure.

