

concrete footings. They upgraded the standards on the new project, which is the one we visited.

They replaced it with this standard, with the same signs now held up by a thicker steel pole, again mounted in concrete, as you see. This still leaves something to be desired, particularly by the person who hits it.

